




# CELLFLEX® Coaxial Cable Connectors


## Installation Instruction

10000037511-02  
SCF12-50 Cables  
ECO Connectors

These instructions are written for qualified and experienced personnel. Please study them carefully before starting any work. Any liability or responsibility for the results of improper or unsafe installation practices is disclaimed. Please respect valid environmental regulations for assembly and waste disposal. Always make sure to use appropriate personal protection!



**Safety precaution: Sharp blade - Protective gloves required.**





## CELLFLEX® Coaxial Cable Connectors

## Installation Instruction

10000037511-02  
SCF12-50 Cables  
ECO Connectors

### Installation method with Universal Trimming Tool



#### TRIM-SET-S12-C02

Consist of:

Body:

Flaring tool:

Insert:

TRIM-U-14-78

----

TRIM-IS12-C02

Insert consist of:

Blade holder:

Collet:

TRIM-IS12-C02

TRIM-IS12

#### Attention:

Trimming tool to be handled and used with great care, blades are extremely sharp!  
It is recommended to use protective gloves. Do not use great force.

**Please refer to the instruction of the Universal Trimming Tool in addition.**

Keep the cable end downwards to prevent particles from entering during preparation.

1. Insert the cable into the Trimming Tool and push against the inner stop as shown. The cable fits properly to the complete insert (collet) of the tool. Close blade housing of the tool.
2. Slowly rotate the Trimming Tool with slight pressure on the blade housing in a clockwise direction as indicated by the arrow on the tool. Open blade housing and remove the cable.
3. Remove the cable jacket and outer conductor. Carefully cut the dielectric lengthwise and remove it.  
**It is imperative to achieve a pure metallic contact surface on the protruding length of the inner conductor.** This may be realized by scrapping away completely all foam and adhesive (thin layer may appear transparent) from the inner conductor manually (fingernail) or with a dedicated tool (e. g. CC200EUR). Take care not to damage the copper cladding, also make sure not to bend the inner conductor out of the straight line.
4. Carefully cut the second part of jacket lengthwise by knife and remove it.
5. Insert the inner conductor into the hole of the chamfer tool, then slowly press and rotate the Trimming Tool clockwise several times to chamfer the inner conductor. Take care not to bend the inner conductor out of the straight line.
6. Double-check trimming dimensions.
7. Remove all edges very carefully; rework the outer conductor, if necessary, to get the outer conductor as a passable thread. It is recommended to check easy turn ability with the back-nut of the connector. Remove back-nut after checking. Clean the cable end, remove all particles very carefully.
8. Place the threaded gasket on outer conductor as shown on picture 8 before screwing to the final position. Screw the threaded gasket onto the prepared outer conductor until reaching a gap of 2-3mm to the jacket as shown. Take care not to damage the gasket.
9. Screw the back-nut onto the outer conductor and over the jacket until the front of back-nut is flush with the cut outer conductor.
10. Clean the prepared cable end; remove any particles very carefully with a brush. It is not recommended to use steel or similar hard brushes, because these can deeply press particles inside the dielectric. Adhesive tape can be used additionally for removing the finest particles.  
**Check the complete preparation (dimensions). Careful preparation is the key to good VSWR and especially to proper PIM performance!**
11. Push and screw connector front part (body) onto prepared cable. Pay attention to align connector parts in one axis while tightening the connector by turning the front part only (first by hand). Do not turn the back-nut or the cable.
12. The copper cover of the cable is 2.0-3.0mm higher than the nut. This is to prevent the cables and connectors from rotating relative to each other.
13. Keep the back-nut and the cable steady and tighten the front part (body) of the connector using open-end wrenches. Tighten the connector properly; recommended torque is 13 Nm.
14. Finish assembly.

